Approved For Release 2001706/15 : CHARDP33-02415A000100390126-8

IDEA-2267-64 Copy 3 of 9

2 December 1964

MEMORANDUM FOR: Deputy for Field Activities, OSA

SUBJECT:

System XIII Cockpit Light

- 1. I strongly recommend that the System XIII cockpit light be removed from the cockpit. The illumination of this lamp has caused confusion ever since installation. If the green lamp on System XII is performing satisfactorily, and recent history has shown that it does, then I fail to see the value of the System XIII lamp.
- 2. Recommendation: That the System XIII lamp be removed from the cockpit on all IDEALAST aircraft.

\$15150 25X1A9a

Chief, Intelligence Division Office of Special Activities

25X1A9a

esr (2 Dec 64)

Distribution:

ID/OSA/

#1 - D/FA/OSA

#2 - AD/OSA

#3 - DAD/OSA

#4 - ASD/OEL

#5 - COMMO/OSA

#6 - IDEA/OSA

#7 - PLANS/OSA

#8 - ID/OSA

#9 - RB/OSA